

PDN# : P723AAB

Issue Date : Feb. 22, 2017

Dear Valued Customer,

ON Semiconductor conducted an analysis of our product portfolio which resulted in the decision to discontinue the products listed in this notification.

Some devices may have an alternate standard device or a suggested replacement as an alternative solution. ON Semiconductor has provided a list of suggested replacement devices in this notice to help customers plan appropriately and effectively for replacement devices.

Customers must notify ON Semiconductor in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS 6 MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. YOUR COMPANY HAS UNTIL Aug. 22, 2017 TO PLACE END-OF-LIFE ORDERS FOR THE LISTED PRODUCT(S).

NOTE: ORDER ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS.

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER 8 MONTHS BEYOND THE ANNOUNCEMENT DATE. ALL DELIVERIES MUST BE SCHEDULED FOR SHIPMENT NO LATER THAN Oct. 22, 2017.

NOTE: ON SEMICONDUCTOR MAY IMPLEMENT MINIMUM ORDER QUANTITIES OR DOLLAR AMOUNTS BASED ON INVENTORIES AVAILABLE. ALSO, DEVICES ON THIS PRODUCT DISCONTINUANCE BECOME NCNR (NON-CANCELABLE, NON-RETURNABLE)

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Sincerely,

ON Semiconductor Corporation



Appendix A: Discontinued Products

Discontinued Product(s):	Suggested Replacement	Manufacturer of Suggested
	Product(s):	Replacement Product(s):
2N7002MTF	2N7002 OR 2N7002L	ON SEMICONDUCTOR
74VHC139CW	NONE	NONE
74VHC139SJX	NONE	NONE
74VHC153M	NONE	NONE
74VHC153MTC	NONE	NONE
74VHC153MTCX	NONE	NONE
74VHC153MX	NONE	NONE
74VHC157SJX	NONE	NONE
74VHC161M	NONE	NONE
74VHC161MTC	NONE	NONE
74VHC161MTCX	NONE	NONE
74VHC161MX	NONE	NONE
74VHC161SJX	NONE	NONE
74VHC221AM	NONE	NONE
74VHC221AMTC	NONE	NONE
74VHC221AMTCX	NONE	NONE
74VHC221AMX	NONE	NONE
74VHC240SJX	NONE	NONE
74VHC27MTCX	NONE	NONE
74VHC27MX	NONE	NONE
74VHC393M	MC74VHC393DG	ON SEMICONDUCTOR
74VHC393MTC	NONE	NONE
74VHC393MTCX	NONE	NONE
74VHC393MX	NONE	NONE
74VHC4040M	NONE	NONE
74VHC4040MTC	NONE	NONE
74VHC4040MTCX	NONE	NONE
74VHC4040MX	NONE	NONE
74VHCT540AMTC	NONE	NONE
74VHCT540AMTCX	NONE	NONE
BAS16HT1G	NONE	NONE
BAT54CWT1G	NONE	NONE
BAT54SWT1G	NONE	NONE
BAV99WT1G	NONE	NONE
FAN54046UCX	FAN54063UCX	ON SEMICONDUCTOR
FAN54300UCX	NONE	NONE
FAN6793MY	NONE	NONE
FDC642P_SB4N006	NTGS3443T1G	ON SEMICONDUCTOR
FDDS10H04A_F085A	NONE	NONE
FDFMA2P857	NONE	NONE



Appendix A: Discontinued Products

II II SCANTINII DA PRAGIICTISI	Suggested Replacement Product(s):	Manufacturer of Suggested Replacement Product(s):
FDMF6706B	FDMF6820B	ON SEMICONDUCTOR
FDMS3660S_F121	FDMS3660S	ON SEMICONDUCTOR
FL7930CMX	FL7930BMX_G	ON SEMICONDUCTOR
FOD2200	HCPL-2200	BROADCOM
FOD2200S	HCPL-2200-300E	BROADCOM
FOD2200SD	HCPL-2200-500E	BROADCOM
FOD2200SDV	HCPL-2200-560E	BROADCOM
FOD2200SV	HCPL-2200-360E	BROADCOM
FOD2200TV	NONE	NONE
FPF1004	FPF1039	ON SEMICONDUCTOR
FPF1014	FPF1013	ON SEMICONDUCTOR
FPF1103	NONE	NONE
FPF1104	FPF1504UCX	ON SEMICONDUCTOR
FPF1205UCX	FPF1203UCX	ON SEMICONDUCTOR
FPF1207UCX	NONE	NONE
FPF1208UCX	NONE	NONE
FPF2174	FPF2172	ON SEMICONDUCTOR
FPF3003UCX	NONE	NONE
FSA8008UMX	FSA8008AUMX	ON SEMICONDUCTOR
FSA8058UMX	FSA8008AUMX	ON SEMICONDUCTOR
FSA9280AUMX_SN00227	FSA9280AUMX	ON SEMICONDUCTOR
FSA9485UCX	NONE	NONE
KSA1156OSTSTU	NONE	NONE
KSA1156YSTSTU	NONE	NONE
MMBZ5228B	MMBZ5228BLT1G	ON SEMICONDUCTOR
MMBZ5247B	MMBZ5247BLT1G	ON SEMICONDUCTOR
NC7ST04L6X	NLU1GT04AMUTCG	ON SEMICONDUCTOR
NC7SV38L6X	NONE	NONE
NC7SV38P5X	NONE	NONE
RURD420S9A_T	MURD320T4G	ON SEMICONDUCTOR